

APPLICATION DATA SHEET

BLACKFAST 517 ACID PICKLE HEAVY

USE: Use as supplied.

APPLICATION: Used undiluted, Blackfast 517 will "crack" the hard skins which form on the surface of very hard steels (60° Rockwell C+) and some unmachined steels such as pressings, drawn tubes.
After treatment in Blackfast 513, the workpiece is immersed in Blackfast 517 for 2-3 minutes, rinsed and returned to Blackfast 513 for removal of any loose smut, which has arisen from Blackfast 517 treatment.

TANK MATERIAL: Tanks should be made of a suitable polypropylene.

PRODUCT SAFETY DATA SHEET: A safety data sheet is available.

Blackfast 517 is part of the Blackfast range of products for the treatment of iron, steel and aluminium at low temperatures.

Blackfast Chemicals continues to improve the quality and performance of its range of products and reserves the right to modify product formulations without prior notice.

OCTOBER 2002